

## **Installing USB Driver for MTS-DCC on Windows 8**

We suggest you print these instructions for reference or view them on another PC while performing the installation.

The drivers included on the CD-ROM may be used with Windows 8 but, as they are unsigned, you must disable driver signature enforcement on your Windows 8 PC. This is not recommended by Microsoft but is required if you wish to use your MTS-DCC with Windows 8.

### **Disable Driver Signature Enforcement**

At the same time, press the "Windows" key and letter "i" to access the settings charm bar (menu) and select "Change PC Settings".

Select "General" in the left hand list, then on the right hand list scroll down until you can see "Advanced Startup" and click "Restart Now".

When Windows restarts, click "Troubleshoot".

Click "Advanced Options".

Click "Startup Settings"

Click "Restart". Windows will restart into the Startup Settings menu.

Press "F7" to "Disable Driver Signature Enforcement"

Your PC will reboot.

You can now successfully load the USB driver.

The following YouTube link is a tutorial showing the steps as outlined above.

<http://www.youtube.com/watch?v=NM1MN8QZhnk>